



SOFOKLI VENIZELOU 41, PERISTERI, GREECE Tel: 210-3421477 ,
Fax: 2103421468, e-mail: info@airquality.com.gr, www.airquality.com.gr

CERTIFICATION

Place / time: New Hotel, located on street Filellinon 16. Cleaning took place in June 2020.

System condition: The water tank's condition was almost good, as it appears from a visual inspection.

To be more specific the cleaning process includes the following areas:

- Emptying of the water tank up until the tank's tap.
- Usage of our water pump for ensuring total void.
- Cleaning with high pressure water (depending on the tanks burden).
- Disinfection using a fogger
- Water tank refill.

We kindly verify that the water tanks of the New Hotel were cleaned properly and disinfected completely.

Kind regards,

Apostolos Giannisopoulos
Mech.Engineer Msc in Energy



SOFOKLI VENIZELOU 41, PERISTERI, GREECE
Tel: + 30 210-3421477, Fax: + 30 210-3421468,

www.airquality.com.gr
sales@airquality.com.gr